

Members are requested to:

- NOTE and CONSIDER the requests from a Resident
- CONSIDER the quotes received for Lydiard Green and Greatfield signs

Background

All the assets mentioned were erected by the PC and are maintained by the PC. An amount was included in the original project capital cost to cover possible future maintenance needs. The signs were designed and specified in collaboration with ASF Signs of Wootton Bassett ASF

Signs and Locations


1. Two redundant signpost poles at the eastern end of Holborn in the grass verge to be removed. They are ugly and not needed. It is location 2 on the map below.

Clerks comment: The Parish Handyman is visiting this site and will advise

2. The Lydiard Green road sign at the eastern end of the hamlet has been damaged and needs replacement. Location 12 on the map. Design shown below.
3. The Greatfield road sign near the crossroads has been damaged and needs renewal. Location 14 on the map. Design is similar to the one for Lydiard Green shown below.

Clerks comment: This sign maybe repairable

4. The Lydiard Millicent sign that should be at location 12 is in store at JCH and should be installed (two new poles required). Clerks comment: There are two signs at JCH and two poles



Clerks Recommendation:
Quotes have been requested
for 2 and 3, although once
Handyman has accessed it is
possible 3 will not be required.

Quotes to be brought to March
meeting for consideration